




Villa no. 05 tile laying work in progress.



Villa no. 01 & 2 back filling work in progress.



Villa no. 3 plinth beam reinforcement work in progress



Villa no.4 plinth beam level back filling work in progress.



Villa no. 6 first floor roof slab concrete work completed.



Villa no 7-2nd floor Column Work in Progress.



Villa no 9 2nd floor, Column work in Progress.



Villa no. 10 G.F Roof slab Shuttering Work in progress.



Villa no. 11 ground floor column concrete works completed.



Villa no 12 ground floor roof slab shuttering work in progress.




Villa no. 14 ground floor column work in progress.



Villa no. 15 ground floor column work in progress.



Villa no. 16 ground floor column work in progress.



Villa no. 18 2nd floor column starter work in progress.



Villa no. 19 plinth beam level back filling work in progress.

Villa no. 20 plinth beam concrete completed.



Villa no.21 plinth beam shuttering work in progress.



Villa no. 22 plinth beam reinforcement work in progress.




Villa no. 23 plinth beam reinforcement work in progress.



Villa no. 39 to 42 villa footing pcc & rcc work in progress.




Villa no. 24 to 30 footing pcc & rcc work in progress.



Villa no. 45 2nd floor column work in progress.



Villa no. 46 first floor slab shuttering work in progress.



Villa no. 47 ground floor column Work in progress.



Villa no 50 & 51 plinth beam level soil back-filling work in progress.




Villa no. 48 footing pcc work in progress.



Villa no 72 first floor roof slab work is completed.



Villa no 70 first floor slab shuttering work in progress.



Villa no 69 ground floor slab completed.



Villa no 81 to 87 back filling work in progress.



Villa no 68 footing short column completed.



Villa no 66 ground floor column starter completed.




Villa no 65 ground floor column starter completed.



Villa no. 91 to 97 plinth beam pcc shuttering work in progress.



Villa no. 88 plinth beam shuttering work in progress.



Villa no. 90 plinth beam completed.