



VILLA NO. 05 MODEL VILLA EXTERNAL TEXTURE WORK IN PROGRESS.



VILLA NO. 01 PEDESTAL COLUMN STARTER WORK IN PROGRESS



VILLA NO.2 PEDESTAL COLUMN CONCRETE COMPLETED.



VILLA NO. 3 & 4 PLINTH BEAM LEVEL BACK FILING WORK IN PROGRESS



VILLA NO. 6 GROUND FLOOR ROOF COMPLETED.



VILLA NO 7 FIRST FLOOR COLUMN SHUTTERING WORK IN PROGRESS.



VILLA NO 9 FIRST FLOOR ROOF SLAB SHUTTERING WORK IN PROGRESS.



VILLA NO. 10 G.F COLUMN WORK IS IN PROGRESS



VILLA NO. 11 PLINTH BEAM SHUTTERING WORK IS IN PROGRESS.



VILLA NO 12 GROUND FLOOR COLUMN REINFORCEMENT WORK IN PROGRESS.



VILLA NO. 14 PLINTH BEAM CONCRETE WORK IS COMPLETED .



VILLA NO. 15 PLINTH BEAM CONCRETE WORK COMPLETED.



VILLA NO. 16 PLINTH BEAM WORK IN PROGRESS.



VILLA NO. 18 FIRST FLOOR SHUTTERING WORK IN PROGRESS



VILLA NO. 19 PLINTH BEAM REINFORCEMENT WORK IN PROGRESS.



VILLA NO. 20 PLINTH BEAM REINFORCEMENT WORK IN PROGRESS.



VILLA NO.21 TO 23 BELOW PLINTH LEVEL SOIL FILLING WORK IN PROGRESS.



VILLA NO. 45 FIRST FLOOR SHUTTERING WORK IN PROGRESS



VILLA NO. 46 FIRST FLOOR COLUMN WORK IN PROGRESS.



VILLA NO. 47 GROUND FLOOR COLUMN REINFORCEMENT WORK IN PROGRESS.



VILLA NO 50 GROUND FLOOR COLUMN STARTER WORK IN PROGRESS.



VILLA NO 51 PLINTH BEAM REINFORCEMENT WORK IN PROGRESS.



VILLA NO. 72 FIRST FLOOR COLUMN CONCRETE COMPLETED



VILLA NO 70 GROUND FLOOR ROOF SLAB CONCRETE COMPLETED.



VILLA NO 69 GROUND FLOOR COLUMN STARTER WORK IN PROGRESS.



VILLA NO 68 FOOTING PCC PREPARATION WORK IN PROGRESS.



VILLA NO 66 GROUND FLOOR COLUMN STARTER COMPLETED.



VILLA NO 65 GROUND FLOOR COLUMN STARTER COMPLETED.



VILLA NO. 81 TO 87 EXCAVATION IS COMPLETED .



VILLA NO 88, 90, 91, 92 BACK FILLING WORK IN PROGRESS.



VILLA NO 96&97 FOOTING SHUTTERING WORK IN PROGRESS.



VILLA NO 93 PEDESTAL COLUMN CONCRETE WORK IN PROGRESS.



VILLA NO 95 PEDESTAL COLUMN STARTER WORK IN PROGRESS.