




VILLA NO. 03 FOOTING PCC WORK IN PROGRESS



VILLA NO. 04 FOOTING REINFORCEMENT WORK IN PROGRESS



VILLA NO. 05 MODEL VILLA AAC BLOCK WORK IN PROGRESS

VILLA NO. 06 TIE BEAM RCC COMPLETED



VILLA NO. 07 G.F COLUMN LAPPING WORK IN PROGRESS




VILLA NO. 09 G.F COLUMN SHUTTERING WORK COMPLETED



VILLA NO.10 TIE BEAM REINFORCEMENT WORK IN PROGRESS



VILLA NO. 11 SOIL SECTIONING FOR CONSOLIDATION WORK COMPLETED



VILLA NO. 12 SOIL COMPACTION WORK COMPLETED UP TO PEDESTAL



VILLA NO. 14 SOIL COMPACTION WORK COMPLETED UP TO PEDESTAL



VILLA NO. 15 SOIL SECTIONING & COMPACTION WORK IN PROGRESS UP TO PEDESTAL.



VILLA NO. 16 BACKFILLING COMPLETED UP TO PEDESTAL COLUMN



VILLA NO. 18 G.F ROOF SLAB SHUTTERING WORK IN PROGRESS



VILLA NO. 19 FOOTING RCC COMPLETED, COLUMN STARTER WORK IN PROGRESS



VILLA NO. 20 FOOTING RCC WORK COMPLETED



VILLA NO. 45 G.F COLUMN SHUTTERING WORK IN PROGRESS



VILLA NO. 46 TIE BEAM SHUTTERING WORK COMPLETED



VILLA NO. 47 SOIL CONSOLIDATION WORK COMPLETED UP TO PEDESTAL.



VILLA NO. 50 SOIL SECTIONING & COMPACTION WORK IN PROGRESS UP TO PEDESTAL COLUMN



VILLA NO. 51 PEDESTAL COLUMN COMPLETED



VILLA NO. 65 SOIL SECTIONING & COMPACTION WORK IN PROGRESS UP TO PEDESTAL COLUMN



VILLA NO. 66 TIE BEAM REINFORCEMENT WORK IN PROGRESS



VILLA NO. 69 BACKFILLING WORK IN PROGRESS UP TO PEDESTAL COLUMN.



VILLA NO. 70 TIE-BEAM RCC WORK COMPLETED



VILLA NO. 72 G.F COLUMN LAPPING WORK IN PROGRESS



VILLA NO. 88, 90, 91, 92, 93, 95 FOOTING PCC WORK COMPLETED



VILLA NO. 72 G.F COLUMN LAPPING WORK IN PROGRESS