

A-Block South side external texture painting work in progress

A-Block West side Texture painting work in progress


A-Block North side external texture painting work in progress



A-Block Cluster-01 UPVC Fixing work in progress



B-Block South side Elevation



B-Block South side texture painting

B-Block west side Painting work in progress



B-Block North side texture painting work in progress



B-Block Cluster-02 Tiles work in progress



B-Block Cluster-02 Terrace clay tile work in progress



C-Block Elevation




C-Block External texture painting work in progress



North side compound wall plastering and Backfilling work in progress



South side compound wall excavation work in progress



DG Yard RC wall shuttering work in progress



Club house Block work completed



Club house external plastering work in progress



STP and WTP Pump room Handrail work in progress



STP and WTP Mechanical work



B-Block Solar panel work in progress



Swimming Pool and Planter box water proofing work in progress