



A-Block South Side Elevation



A-Block West Side Elevation



A-Block Basement Screed Concrete Work Completed



A-Block Cluster-01 Terrace Clay Tile Work In Progress



A-Block Common Staircase Handrail Work In Progress



A-Block Common Staircase Handrail Work In Progress



Basement Painting Work in Progress



B-Block North Side Elevation



B-Block West Side Elevation



B-Block North Elevation



Planter Box Water Proofing Work in Progress



Solar Provision Work in Progress



C-Block West Side Elevation



C-Block North Side External Painting



Club House External Painting Work in Progress



Club House Internal Putty Work in Progress



Entry Portal Structural Work in Progress



Pool Deck Area Cinder Filling Work in Progress



South Side Compound Wall RCC Work in Progress



West Side Compound Wall Block Work in Progress



STP and WTP Machinery Work