




A-Block south side elevation



A-Block cluster-03 south side external plastering work in progress



A-Block west side elevation



A-Block cluster-01, 02 north side external plastering




A-Block cluster-01, 02 ots external plastering completed



A-Block cluster-02 internal wall first coat putty work in progress



A-Block cluster-01 common staircase granite work in progress



B-Block south side elevation



B-Block cluster-01, 02 external plastering completed



B-Block cluster-01, 02 OTS External plastering completed



B-Block west side elevation

B-Block cluster-01 terrace waterproofing work in progress



B-Block cluster-02 internal 1st coat putty work in progress



B-Block cluster-01 tiles laying work in progress



B-Block cluster-01 common staircase granite work in progress



Internal staircase handrail work completed – model flat



Internal staircase handrail work completed – model flat



C-Block West side elevation



C-Block south side External plastering



North side compound wall shuttering work in progress