

RADIANE
IMPERIA



Villa No. 05 Model Villa


RADIANCE
IMPERIA



Villa No. 05 Model Villa




Villa no. 1 First Floor Column Work in Progress



Villa no. 2 First Floor Column Completed



Villa no. 3 first floor Slab Shuttering Work in Progress



Villa 04 2nd Floor Column Work in Progress



Villa 31 Back Filling Work in Progress



Villa 6 Block Work in Progress




Villa 30 Plinth Beam Reinforcement Work in progress



Villa 7 Block Work in Progress




Villa 29 Plinth Beam Reinforcement Work in Progress



Villa 9 Block Work in Progress




Villa 28 Plinth Beam Reinforcement Work in Progress



Villa 10 Block Work in Progress



Villa 27 Plinth Beam Level Soil Filling Work in Progress



Villa 11 Block Work in Progress




Villa 25 Plinth Beam Level Soil Filling Work in Progress




Villa 24 Plinth Beam Level Soil Filling Work in Progress



Villa 12 Block Work in Progress




Villa 14 Block Work in Progress




Villa 23 Ground Floor Column Work Completed



Villa 15 Block Work in Progress



Villa 22 Ground Floor Roof Slab Work in Progress



Villa 16 Block Work in Progress




Villa 21 First Floor Column Work in progress



Villa 18 Block Work in Progress



Villa 19 & 20 Ground Floor Column Work in Progress




Villa 43 Plinth Beam Work in Progress




Villa 42 Plinth Beam Work in Progress


RADIANCE
IMPERIA



Villa 45 Block Work in Progress



Villa-46 Block Work in Progress



Villa-47 Block Work in Progress




Villa-48 First Floor Roof Shuttering Work in Progress




Villa-41 Ground Floor Roof Shuttering Work in Progress



Villa-50 2nd Floor Column Work in Progress



Villa-40 1st Floor Column Work in Progress



Villa-51 1st Floor Roof Completed




Villa-39 Ground Floor Roof Slab Shuttering Work in Progress




Villa- 38 to 32 Backfilling Work in Progress



Villa- 65 2nd Floor Column Work in Progress




Villas 79-75: Soil compaction work in progress



Villas-66 2nd Floor Column Work in Progress




Villas-68 1st Floor Column Completed



Villas-69 Block Work in Progress


RADIANE 
IMPERIA



Villas-72 Block Work in Progress



Villas-72 Block Work in Progress




Villas-73 Plinth Beam Concrete Work Completed



Villas-74 Plinth Beam Reinforcement Work in Progress



Villas-88 2nd Floor Column Work in Progress



Villas-87 1st Floor Column Work in Progress



Villas-90 2nd Floor Column Work in Progress



Villas- 86 First Floor Roof Slab Completed




Villas- 91 First Floor Roof Slab Completed




Villas- 84 First Floor Roof Slab Shuttering Work in progress




Villas- 92 1st Floor Roof Completed




Villas- 83 1st Floor Column Work in Progress



Villas- 93 1st Floor Column completed



Villas- 82 1st Floor Column Work in Progress



Villas- 95 1st Floor Column Work in Progress



Villas- 81 1st Floor Column Work in Progress



Villas- 96 1st Floor Column Work in Progress




Villas- 97 1st Floor Column Work in Progress



Villas- 52 Ground Floor Roof Slab Shuttering work in progress



Villas- 54 Ground Floor Column Completed



Villas- 56 Ground Floor Column Work in Progress



Villas- 57 Ground Floor Column Work in Progress



Villas- 59 Ground Floor Column Work in Progress



Villas- 60 Ground Floor Column Work in Progress



Villas- 61 Plinth Beam Completed



Villas- 62 Plinth Beam Shuttering Work in Progress



Villas- 63 Plinth Beam Shuttering Work in Progress



Villa 64: Plinth beam soil sectioning work in progress



STP & WTP Wall Reinforcement Work in Progress