
RADIANCE IMPERIA




Villa No. 1 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 2 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 3 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 4 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 5 – Model Villa - Completed (View 1 of 2)

RADIANCE IMPERIA



Villa No. 5 – Model Villa - Completed (View 2 of 2)

RADIANCE IMPERIA



Villa No. 6 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 7 – Internal Wall Putty Work in Progress

RADIANCE IMPERIA



Villa No. 9 – Internal Wall Putty Work in Progress

RADIANCE IMPERIA



Villa No. 10 – Plastering Work Completed

RADIANCE IMPERIA



Villa No. 11 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 12 – Internal Wall Putty Work in Progress

RADIANCE IMPERIA



Villa No. 14 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 15 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 16 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 18 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 19 – First Floor Roof Slab Shuttering Work in Progress

RADIANCE IMPERIA




Villa No. 20 – First Floor Roof Slab Completed

RADIANCE IMPERIA




Villa No. 21 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 22 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 23 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 24 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 25 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 27 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 28 – Second Floor Roof Slab Completed

RADIANCE IMPERIA




Villa No. 29 – Second Floor Roof Slab Work in Progress

RADIANCE IMPERIA



Villa No. 30 – Second Floor Roof Slab Completed

RADIANCE IMPERIA



Villa No. 31 – Second Floor Roof Slab Completed

RADIANCE IMPERIA




Villa No. 32 – First Floor Column Work in Progress

RADIANCE IMPERIA




Villa No. 33 – Second Floor Column Work in Progress

RADIANCE IMPERIA



Villa No. 34 – Second Floor Column Work in Progress

RADIANCE IMPERIA




Villa No. 36 – Second Floor Roof Slab Work in Progress

RADIANCE IMPERIA




Villa No. 37 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 38 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 39 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 40 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 41 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 42 – Second Floor Column Work in Progress

RADIANCE IMPERIA



Villa No. 43 – First Floor Roof Slab Shuttering Work in Progress

RADIANCE IMPERIA



Villa No. 45 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 46 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 47 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 48 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 50 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 51 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 52 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 54 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 55 – Block Work in Progress

RADIANCE
IMPERIA



Villa No. 55 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 56 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 57 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 59 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 60 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 61 – Second Floor Roof Slab Concrete Work in Progress

RADIANCE IMPERIA



Villa No. 63 – Second Floor Roof Slab Shuttering Work in Progress

RADIANCE IMPERIA




Villa No. 64 – Second Floor Column Work in Progress

RADIANCE IMPERIA



Villa No. 65 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 66 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 68 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 69 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 70 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 72 – Plastering Work in Progress

RADIANCE IMPERIA



Villa No. 73 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 74 – Second Floor Roof Slab Completed

RADIANCE IMPERIA




Villa No. 75 – Second Floor Roof Slab Completed

RADIANCE IMPERIA




Villa No. 77 – Second Floor Roof Slab Completed

RADIANCE IMPERIA




Villa No. 78 – Second Floor Roof Slab Completed

RADIANCE IMPERIA




Villa No. 79 – Second Floor Roof Slab Completed

RADIANCE IMPERIA




Villa No. 81 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 82 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 83 – Plastering Work in Progress

RADIANCE IMPERIA




Villa No. 84 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 86 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 87 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 88 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 90 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 91 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 92 – Block Work in Progress

RADIANCE IMPERIA




Villa No. 93 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 95 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 96 – Block Work in Progress

RADIANCE IMPERIA



Villa No. 97 – Block Work in Progress

RADIANCE IMPERIA



STP & WTP – Base Slab Shuttering and Reinforcement Work in Progress

RADIANCE IMPERIA



Club House – Footing and Column Starter Work in Progress