

RADIANCE
Platinum

B1004

B1005

Block - B

B1003

East

West

A1002

Block - A

A1001

Master View





Block A - 9th Floor Roof Slab Reinforcement Work (A1001,A1002)



Block A - 9th Floor Roof Slab Reinforcement Work (A1001,A1002)



Block B - 9th Floor Roof Slab Reinforcement Work (B1003,b1004,B1005)



Block B - 9th Floor Roof Slab Reinforcement Work (B1003,b1004,B1005)



6th Floor Block Work




7th Floor Block Work



4th Floor Electrical Work



2nd Floor Internal Wall Plastering Work



3rd Floor Internal Wall Plastering Work



Compound Wall - East Side



Compound Wall - North Side

RADIANCE
Platinum



West Side



South Side



North Side

RADIANCE
Platinum



East Side

RADIANCE
Platinum



South West Corner View

RADIANCE
Platinum



North West Corner View

RADIANCE
Platinum



North East Corner View



West Elevation

RADIANCE
Platinum




North Elevation

RADIANCE
Platinum



South Elevation

RADIANCE
Platinum



East Elevation

RADIANCE
Platinum

Block A - 9th Floor Roof Slab (A1001 & A1002)



Block - B - 9th Floor Roof Slab - B1003, B1004 & B1005

15-03-26 10 21-03-26



RADIANCE
Platinum

22-03-26 10 28-03-26



Master View

RADIANCE
Platinum



Master View