



ENTRY PORTAL GATE FIXING WORK COMPLETED





CLUBHOUSE TO VILLA NO.04 PAVER LAYING WORK COMPLETED.





CLUBHOUSE TILING, MEP, & AC WORK IN PROGRESS.





VILLA NO.01 TO 04 CAR PARKING & DECK AREA SCREED WORK IN PROGRESS.





PAVER LAYING WORK IN PROGRESS NEAR VILLA NO. 04 TO VILLA NO. 16





VILLA NO. 5 TO 9 LOUVERS WORK & STEPS GRANITE WORK IN PROGRESS.





VILLA NO. 10 TO 16 ROAD SEWAGE LINE WORK IN PROGRESS.





VILLA NO. 10 TO 18 INTERNAL TILE WORK IN PROGRESS.





VILLA NO. 16 TO 20 ROAD PAVER WORK IN PROGRESS.





VILLA NO.19 TO 25 LOUVERS SCAFFOLDING WORK IN PROGRESS.





VILLA NO. 27 TO 33 CAR PARKING TILING, ELECTRICAL CHAMBER WORK IN PROGRESS.





VILLA NO. 34 TO 41 CAR PARKING CHAMBER, INTERNAL PAINTING WORK IN PROGRESS.





VILLA NO. 42 TO 50 CRM HANDING OVER WORK IN PROGRESS.





VILLA NO. 34 TO 50 PAVER COMPLETED, DEBRIS CLEANING WORK IN PROGRESS.





VILLA NO. 25 TO 59 ROAD PAVER COMPLETED, RAIN WATER HARVESTING PIT COMPLETED.





VILLA NO. 51 TO 59 CRM HANDOVER COMPLETED.





VILLA NO. 60 TO 65 CRM SNAG WORK IN PROGRESS.





VILLA NO. 51 TO 65 PAVER COMPLETED , RAIN WATER HARVESTING PIT COMPLETED.





LANDSCAPING AREA SOIL SECTIONING WORK IN PROGRESS.





VILLA 66 TO 78 ROAD DEBRIS CLEANING WORK IN PROGRESS.





VILLA NO. 66 TO 72 CRM SNAG WORK IN PROGRESS.





VILLA NO. 73 TO 78 CAR PARKING TILE WORK, INTERNAL PAINTING WORK IN PROGRESS.





ROAD WORK COMPLETED.





VILLA NO. 79 TO 84 EXTERNAL PLUMBING & INTERNAL PAINTING WORK IN PROGRESS.





VILLA 79 TO 84 ROAD PAVER COMPLETED, RAINWATER HARVESTING PIT COMPLETED.





VILLA NO. 86 TO 92 ACID WASH & TILE GROUTING WORK IN PROGRESS.





VILLA NO. 93 TO 100 ACID WASH & TILE GROUTING WORK IN PROGRESS.





VILLA 93 TO 100 ROAD PAVER WORK COMPLETED, LANDSCAPE SOIL FILLING WORK IN PROGRESS.





VILLA NO. 101 TO 106 , 120 TO 126 AREA ROAD WORK COMPLETED.





VILLA NO. 101 TO 106 CRM HANDOVER COMPLETED.





VILLA NO. 108 TO 113 CRM SNAG WORK IN PROGRESS.





VILLA NO. 114 TO 119 INTERNAL PAINTING WORK IN PROGRESS.





VILLA NO. 108 TO 119 ROAD PAVER COMPLETED.





VILLA NO. 120 TO 126 CRM HANDOVER COMPLETED.





VILLA NO. 127 TO 132 CRM SNAG WORK, ELECTRICAL CHAMBER WORK IN PROGRESS.





VILLA NO. 133 TO 144 ROAD SEWAGE LINE CHAMBER WORK IN PROGRESS.





VILLA NO. 133 TO 138 TILE GROUTING WORK IN PROGRESS.





VILLA NO. 140 TO 144 INTERNAL TILE WORK, CAR PARKING AREA CONCRETE WORK IN PROGRESS.





VILLA NO. 145 TO 150 TILE WORK & CUSTOMIZATION WORK IN PROGRESS.





DG INSTALLATION WORK COMPLETED.





DRIVERS TOILET INTERNAL PLASTERING WORK COMPLETED.





ORGANIC WASTE COMPOSTER YARD.





EXIT GATE FIXING WORK COMPLETED.





RAINWATER HARVESTING PITS.





RAINWATER HARVESTING PITS.





OSR – 1 COMPOUND WALL GRILL WORK, PATHWAY BLOCK WORK IN PROGRESS.





OSR – 2 COMPOUND WALL GRILL WORK IN PROGRESS





OSR – 3 OSR WORK IN PROGRESS.