

Elevation Block A



Elevation Block 1 Podium




Elevation Block 1 E & F



Block 1 –Cluster A UPVC Fixing work In Progress



Block 1 -Cluster A Putty work In Progress



Block 1 –Cluster B Jams Tile work in progress



Block 1 –Cluster B Ceiling Putty work in progress




Block 1 - Cluster B Tile work in progress



Block 1 -Cluster D Touchup Work In Progress



Block 1 – Cluster D 1st Coat Painting Work In Progress



Block 1 - Cluster D Balcony Upstand Finishing Work In Progress



Block 1 –Cluster D Grouting Work In Progress



Block 1 –Cluster C Staircase granite Skirting Polish Work In Progress



Block 1 –Cluster D Lift Granite Cladding Work In Progress



Cluster E Kitchen Counter Putty Work in Progress



Cluster E Skirting Above Plastering Work in Progress



Block 1-F 1coat paint preparation Work In Progress



Block 2 –Cluster G Tiles Laying Work In Progress



Block 2 –Cluster G Putty Work In Progress



Block 2 -Cluster G External Plastering Work In Progress




Block H & J Grouting work in progress



Block 3 – Cluster H & J Touch Up Work In Progress



Block H & J Terrace Polycarbonate covering Work In Progress




H & J OTS Tile Laying Work In Progress



Water Meater Fixing Work In Progress



Grano Flooring Work In Progress



Entry Portal Slab Work Completed



STP Tank Top Water Proofing Coating Work In Progress



Strom Water Drain Excavation & Dressing Work In Progress