




Block 1 – Cluster a kitchen plastering work in progress



Block 1 - Cluster a gypsum work in progress



Block 1 – Cluster a west side external plastering work in progress




Block 1 – Cluster B 1st floor gypsum work in progress



Block 1 – Cluster B ceiling putty work in progress



Block 1 – Cluster C tile work in progress



Block 1 – Cluster d ceiling & wall putty & primer work in progress




Block 1 –Cluster D tile laying work In progress



Block 1 – Cluster D tile laying work in progress



Cluster e ceiling & wall putty work in progress




Cluster E tile work in progress



Block 1 – Cluster F staircase granite work in progress




Block 1 – Cluster F doors & frames work in progress



Block 2 – Cluster G 3rd floor block work In progress



Block 3 – Cluster H external texture painting work in progress



Block 3 – Cluster H external texture painting work in progress




Block 3 – Cluster J & H stilt floor putty work in progress



Lorem Ipsum

Block 3 – Cluster J terrace tile laying work in progress



Basement screed concrete work in progress



North side compound wall work in progress